

General Environmental Incident Summary

Incident: 3675 **Date/Time Notice:** 3/4/2015 10:55 **DEM Incident No:**

Responsible Party: Frankies West

Date Incident: 3/4/2015 **Time Incident:** **Duration:**

County: Stark **Twp:** 139 **Rng:** 96 **Sec:** 3 **Qtr:**

Lat: 46.88608 **Long:** -102.78840 **Method:** Interpolation from map

Location Description: Frankies Westside
1554 West Villard
Dickinson ND 58601

Submitted By: Russ Steier

Affiliation: Part Owner

Address: 2002 5th Street West

City: Dickinson

State: ND

Zip: 58601

Received By:

Contact Person: Russ Steier
1154 West Villard
Dickinson, ND 58601

Distance Nearest Occupied Building: 50 Feet

Release Contained: Yes

Type of Incident:

Description of Released Contaminant: Petroleum Product

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

We were selling the store. We did a phase two study. We did 8 bores. Found B-2 contained THP-DRO at concentration 145 milligrams per kilogram.

Risk Evaluation:

none

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

Spread floor dry and pick-up.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/4/2015

Status: Reviewed; Followup Required

Staff: Martin, Russell

Updated Volume:

Notes:

According to report contact, this did not involve an underground storage tank. Followup necessary.

Date: 3/4/2015

Status: Phone/Email Contact

Staff: Suess, Bill

Updated Volume:

Notes:

Contacted Russ Steier and requested that he forward a copy of Phase II to the NDDoH for review.